
Check temp sensor connectot


• We will work on better manuals. If you have any questions contact us on support@roestcoffee.com





Take of top but be aware the cable that must be disconnected





If they are soldered just check the connector. If they are not soldered you can press down the cables with a screwdriver. Like below.

